


## Installation of the CHIP in the toner cartridge for Lexmark™ Optra™ T/Se



1. Remove the adhesive protection and press the sticky face against the plastic to ensure that the chip is properly attached.



2. Please control that the encoder wheel is like this one

### **Possible faults**

- 1- The new chip has been damaged
- 2- The OEM chip is damaged
- 3- The new chip is in the wrong position

### **TESTING THE OEM CHIP**

To test the OEM chip, you have to try the cartridge without our chip.  
If the printer does not allow you to print anything, the OEM chip is faulty.  
If the printer prints out test pages, the OEM chip is OK to use.